

# DEPARTMENT OF NATURAL RESOURCES DIVISION OF OIL, GAS AND MINING

Michael O. Leavitt PO Box 145801 Governor

Executive Director Lowell P. Braxton

Kathleen Clarke Division Director

1594 West North Temple, Suite 1210 Salt Lake City, Utah 84114-5801

801-538-5340 801-359-3940 (Fax) 801-538-7223 (TDD)

# INSPECTION REPORT

Partial: XXX	Complete:	Exploration:
Inspection Date &	Time: 424700	11 / 10:00am-3:00pm
•	st Inspection: 3	

Mine Name: SUFCO Mine	County: Sevier	Permit Number:	<b>5</b> 51.002				
Permittee and/or Operator's Nam	e: Canyon Fuel Company						
Business Address: 397 South 8	00 West, Salina, Utah 84564						
Type of Mining Activity: Underg	ground XXX Surface	Prep. Plant	Other				
Company Official(s): Mike Day	vis						
State Official(s): Stephen J. Demczak Federal Official(s): None							
Weather Conditions: Warm, 60	<u>'s</u>						
Existing Acreage: Permitted 23	<u>5,970.03</u> Disturbed <u>70.189</u>	Regraded	Seeded				
Status: Active XXX							

# REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

- Substantiate the elements on this inspection by checking the appropriate performance standard.
  - For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
  - For <u>partial inspections</u> check only the elements evaluated.
- Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
- Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
- Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

		EVALUATED	<u>N/A</u>	COMMENTS	NOV/ENE
1.	PERMITS, CHANGE, TRANSFER, RENEWAL, SALE	[X]	$\Box$	[X]	$\Box$
2.	SIGNS AND MARKERS	$\Box$	$\Box$	$\Box$	$\Box$
3.	TOPSOIL	[X]	$\Box$	[X]	$\Box$
4.	HYDROLOGIC BALANCE:				
	a. DIVERSIONS	[X]	$\Box$	[X]	$\Box$
	b. SEDIMENT PONDS AND IMPOUNDMENTS	[X]	$\Box$	[X]	$\Box$
	c. OTHER SEDIMENT CONTROL MEASURES	[X]	$\Box$	[X]	$\Box$
	d. WATER MONITORING	[X]	$\Box$	[X]	$\Box$
	e. EFFLUENT LIMITATIONS	$\Box$	П	$\Box$	$\Box$
5.	EXPLOSIVES	П	$\Box$	$\Box$	$\Box$
6.	DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES	$\Box$	$\Box$		$\Box$
7.	COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS	[X]	$\Box$	[X]	$\Box$
8.	NONCOAL WASTE	[X]	$\Box$	[X]	$\Box$
9.	PROTECTION OF FISH, WILDLIFE AND RELATE				
	ENVIRONMENTAL ISSUESD	$\Box$	$\Box$		$\Box$
10.	SLIDES AND OTHER DAMAGE			П	$\Box$
11.	CONTEMPORANEOUS RECLAMATION		$\Box$	$\Box$	
12.	BACKFILLING AND GRADING	$\Box$	$\Box$	П	П
13.	REVEGETATION	$\Box$	$\Box$		
14.	SUBSIDENCE CONTROL	[X]	$\Box$	[X]	
15.	CESSATION OF OPERATIONS	$\Box$	$\Box$	П	. []
16.	ROADS:				
	a. CONSTRUCTION/MAINTENANCE/SURFACING	П	$\Box$	$\Box$	П
	b. DRAINAGE CONTROLS	П	$\Box$	П	
17.	OTHER TRANSPORTATION FACILITIES	П	$\Box$	$\Box$	$\Box$
	SUPPORT FACILITIES/UTILITY INSTALLATIONS	[X]	$\Box$	[X]	Ц
	AVS CHECK (4th Quarter- April, May, June)	$\Box$	$\Box$		П
20.	AIR QUALITY PERMIT	П	$\Box$	П	П
21	RONDING & INSURANCE	[]	[ ]	[ ]	[]

#### INSPECTION REPORT

(Continuation sheet)

PERMIT NUMBER: C/041/002

DATE OF INSPECTION: 04/25/2001

( COMMENTS ARE NUMBERED TO CORRESPOND WITH TOPICS LISTED ABOVE )

# 1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE

The permittee has plans to submit an amendment that will request installation of two water tanks within the permit area. These tanks would be used for fire suppression. The exact location has not been determined.

#### 3. TOPSOIL

The topsoil and subsoil piles at the refuse site have been inspected with no signs of erosion occurring. This is the first time a visual inspection was made since the third quarter due to snow cover.

## 4A. HYDROLOGIC BALANCE: DIVERSIONS

Diversions were spot-checked and were found to function as designed.

## 4B. HYDROLOGIC BALANCE: SEDIMENT PONDS AND IMPOUNDMENTS

The sediment ponds at the refuse site did contain water, but it is not likely they will discharge in the near future.

# 4C. HYDROLOGIC BALANCE: OTHER SEDIMENT CONTROL MEASURES

Several silt fences were inspected and were found to function as designed.

# 4D. HYDROLOGIC BALANCE: WATER MONITORING

The permittee has submitted fourth quarter water monitoring to the Division. This information has been accepted and was reviewed by the inspector. The information was found to be complete and complies with the requirements within the permit. The first quarter information is currently being compiled.

## 7. COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS

There were no hazardous conditions noticed during the inspection. The permitted have dumped several truck loads of refuse off the side of the refuse pile. This material will be compacted when enough material has been accumulated.

## **INSPECTION REPORT**

(Continuation sheet)

PERMIT NUMBER: C/041/002

DATE OF INSPECTION: <u>04/25/2001</u>

#### 8. NONCOAL WASTE

The permittee has finished spring cleaning of non-coal waste material from the disturbed area. This was a positive improvement from the last month's inspection. There were no signs of trash, opened oil cans, broken pallets, or other debris at the mine site. The parking lot did not even have empty pop containers. The property looked good.

# 14. SUBSIDENCE CONTROL

The permittee has submitted the information within the annual report to the Division.

# 18. SUPPORT FACILITIES/UTILITY INSTALLATIONS

No new support facilities were added since the last inspection.

An inspection to the leach field was made. There were no signs of varmint holes within the leach field. This caused the leach field to leak waste water in the past. The leach field will need to be monitored. If the rock chucks enter the area, then removing them will most likely be necessary.

Inspector's Signature:

Stephen J. Demczak #39

Date: April 26, 2001

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas & Mining.

sd

cc: James F

James Fulton, OSM Ken May, Canyon Fuel

Price Field office

O:\041002.CON\Compliance\2001\p\_0425.wpd